
TVF&R LOGISTICS SERVICE CENTER

ARCHITECTURAL REVIEW PLANS



VICINITY MAP NOT TO SCALE

LEGEND PROPOSED STORM SEWER CLEAN OUT DECIDUOUS TREE STORM SEWER CATCH BASIN CONIFEROUS TREE STORM SEWER AREA DRAIN FIRE HYDRANT GAS METER WATER BLOWOFF GAS VALVE WATER METER **GUY WIRE ANCHOR** WATER VALVE DOUBLE CHECK VALVE P POWER VAULT AIR RELEASE VALVE POWER JUNCTION BOX SANITARY SEWER CLEAN OUT O POWER PEDESTAL COMMUNICATIONS VAULT COMMUNICATIONS JUNCTION BOX COMMUNICATIONS RISER **EXISTING** <u>PROPOSED</u> RIGHT-OF-WAY LINE **BOUNDARY LINE** PROPERTY LINE CENTERLINE EDGE OF PAVEMENT EASEMENT FENCE LINE GRAVEL EDGE POWER LINE OVERHEAD WIRE COMMUNICATIONS LINE FIBER OPTIC LINE STORM SEWER LINE SANITARY SEWER LINE WATER LINE



SITE MAP SCALE: 1" = 200'

SHEET INDEX

P7

Р8

COVER SHEET WITH VICINITY AND SITE MAP PRELIMINARY EXISTING CONDITIONS PLAN PRELIMINARY SITE PLAN P3 PRELIMINARY GRADING PLAN PRELIMINARY TREE PRESERVATION PLAN PRELIMINARY TREE PRESERVATION TABLE

PRELIMINARY LANDSCAPE PLAN

PRELIMINARY PUBLIC FACILITIES PLAN

PROJECT TEAM

CONTRACTOR/CLIENT

EMERICK CONSTRUCTION CO. 7855 SW MOHAWK STREET TUALATIN, OR 97062

CIVIL ENGINEERING/SURVEYING/

AKS ENGINEERING & FORESTRY, LLC. 12965 SW HERMAN ROAD, SUITE 100 TUALATIN, OR 97062 CONTACT: MIMI DOUKAS, AICP, RLA PH: 503-563-6151

MERRYMAN BARNES ARCHITECTS INC. 4713 N ALBINA AVENUE, SUITE 304 PORTLAND, OR 97217

PROJECT DESCRIPTION

TVF&R LOGISTICS SERVICE CENTER

9991 SW AVERY STREET TUALATIN, OR 97062

PROPERTY DESCRIPTION:

TAX LOT 200 (WASHINGTON COUNTY TAX ASSESSOR'S MAP 2S 1 26BA) LOCATED IN THE NORTHWEST 1/4 OF SECTION 26, TOWNSHIP 2 SOUTH, RANGE 1 WEST, WILLAMETTE MÉRIDIAN, CITY OF TUALATIN, WASHINGTON

APPLICANT/OWNER

TUALATIN VALLEY FIRE & RESCUE 11945 SW 70TH AVENUE TIGARD, OR 97223

PLANNING/LANDSCAPE ARCHITECTURE

FAX: 503-563-6152

ARCHITECTURE

ELECTRICAL ENGINEERING


INTERFACE ENGINEERING 100 SW MAIN STREET, SUITE 1600 PORTLAND, OR 97204

PROJECT ADDRESS

COUNTY, OREGON.

JOB NUMBER 5736

> SHEET **P1**



PRELIMINA EXISTING


DESIGNED BY: AS NOTED

DATE: 5/3/2019

JANUARY 12, 2016
MOTAL S. KALINA
89558PLS RENEWS: 6/30/19

JOB NUMBER 5736

SHEET



Q 出 S \Box 4 Ž Ž


AS NOTED

R

Ω

JOB NUMBER

5736 SHEET





PRELIMINARY GRADING PLAN

AS NOTED

JOB NUMBER **5736**

SHEET **P4**





- 1. CHAIN LINK FENCE FOR TREE PROTECTION DEVICE OR
- APPROVED EQUAL. 2. AVOID DAMAGE TO CRITICAL ROOT ZONE. DO NOT DAMAGE OR SEVER LARGE ROOTS WHEN INSTALLING POSTS.
- 3. DEVICE SHALL BE MAINTAINED THROUGHOUT CONSTRUCTION. TREE PROTECTION FENCE


- ENCROACHMENTS (GRADING, CONSTRUCTION, ETC.) INTO OPTIMAL TREE ROOT ZONES OUTSIDE OF THE TREE PROTECTION AREA OF TREES TO BE PRESERVED AS SHOWN SHOULD NOT HAVE SIGNIFICANT NEGATIVE IMPACTS TO TREE HEALTH. THIS PLAN HAS BEEN REVIEWED BY A CERTIFIED ARBORIST PER TDC 73.250(2)(E).
- GRADING ACTIVITIES SHALL NOT INCLUDE ALLOWING TREE ROOTS FROM PRESERVED TREES TO REMAIN EXPOSED PER TDC 73.250(2)(F).
- 3. PER TDC 31.060, A TREE IS DEFINED AS AT LEAST EIGHT (8) INCHES IN DIAMETER AT BREAST HEIGHT (DBH). THEREFORE, ALL TREES WITH A DBH OF 8 INCHES OR GREATER ARE SHOWN. SOME ADDITIONAL TREES UNDER 8 INCHES IN DBH ARE SHOWN. SEE SHEET P6 FOR ADDITIONAL INFORMATION.
- 4. PER TDC 33.110(4)(b)(iii), EACH TREE PROPOSED FOR REMOVAL IS BEING REMOVED TO FACILITATE PROPOSED IMPROVEMENTS OR BECAUSE IT IS IN POOR CONDITION.

LEGEND

EXISTING GROUND CONTOUR (1 FT) EXISTING GROUND CONTOUR (5 FT) FINISHED GRADE CONTOUR (1 FT) FINISHED GRADE CONTOUR (5 FT) <u>_________150 ______</u> 於 EXISTING CONIFEROUS TREE \odot EXISTING DECIDUOUS TREE TREE REMOVAL TREE PROTECTION FENCE

(TREE PROTECTION AREA)

~~~~~



DAVID J. STEINKE, CERTIFIED ARBORIST PN-8112A AKS ENGINEERING & FORESTRY STEINKED@AKS-ENG.COM


I, DAVID J. STEINKE, ATTEST THAT

REMOVAL PLAN IS IN ACCORDANCE

WITH TYPICAL ARBORICULTURAL AND

THIS TREE PRESERVATION AND

URBAN FORESTRY STANDARDS.



JOB NUMBER

5736 SHEET

ORE

PLAN

ARY TIO

R\

PRESE

AS NOTED

PRELIMIN

DATE: 5/3/2019

0

Detailed Tree Inventory for TVF&R Logistics Service Center

		DDII	luation Date: 1/	•		He alt b	C+	D *
Tr	ree#	DBH (in.)	Avg. Crown Radius (ft)	Tree Species Common Name (<i>Scientific name</i>)	Comments	Health Rating*	Structure Rating**	Reason for Removal**
10	0583	8	9	Plum (Prunus sp.)	OFFSITE; Crooked; Decay; Exposed roots	2	2	Preserve
	0587	8	9	Maple (Acer sp.)	OFFSITE; Crooked; Decay; Exposed roots; Many branches attached at one point	2	2	Preserve
	0592	7	7	Maple (Acer sp.)	OFFSITE; Many exposed roots	1	2	Preserve
	0629	7	10	Maple (Acer sp.)	OFFSITE; Many exposed roots	1	2	Improvemen
	0630	30	25	Black Oak (Quercus kelloggii)	Many branches attached at one point; Some dead and broken branches	2	2	Improvemen
	0631	8	9	Prunus (<i>Prunus sp.</i>)	Codominant with ~2' of included bark; Cracks; Decay	2	2	Improvemen
	0632	7	8	Maple (Acer sp.)	OFFSITE; Many exposed roots	1	2	Improvemen
	0633	10	8	Maple (Acer sp.)	OFFSITE; Many exposed roots	1	2	Improvemer
	0634	19	18	Pine (Pinus sp.)	Girdled roots; Pruned; Sap flow; Dead and broken branches	2	2	Improvemer
	0635	30	29	Black Oak (Quercus kelloggii)	Pruned; Some dead and broken branches; Some decay; Exposed roots	2	2	Improvemer
	0637	21	21	Pine (Pinus sp.)	Lean (SE); Pruned; Codominant top; Sap flow; Exposed roots	2	2	Improveme
	0638	12	18	Pine (Pinus sp.)	Crooked; Exposed roots; Canopy one sided (S); Crooked	2	2	Improveme
	0643	11	13	Plum (<i>Prunus sp.</i>)	OFFSITE; Lean (S); Many large exposed roots; Pruned; Decay; Sucker shoots	3	3	Poor Condit
	0648	14	15	Plum (<i>Prunus sp.</i>)	OFFSITE; Many large exposed roots; Broken branches; Cracks; Decay; Topped	3	3	Poor Condi
	0658	7	8	Plum (<i>Prunus sp.</i>)	Pruned; Bulges; Decay; Root collar swell; Bore holes	2	3	Improveme
	0806	9	10	Maple (Acer sp.)	OFFSITE; Pruned	1	1	Preserve
		9	10			1	1	
	0807			Maple (Acer sp.)	OFFSITE; Pruned			Preserve
	0870	10	12	Spruce (Picea sp.)	Topped for overhead wires; Evaluation from right-of-way	2	3	Preserve
	0885	16	12	Pine (Pinus sp.)	Codominant top with included bark; Pruned; Sap flow; Crooked	2	2	Improveme
	0886	12	12	Pine (Pinus sp.)	Lean (S); Crooked; Suppressed; Pruned	2	2	Improveme
	0900	16	15	Pine (<i>Pinus sp.</i>)	Pruned; Crooked; Codominant top; Sparse foliage	2	2	Improvem
	0901	22	18	Pine (<i>Pinus sp.</i>)	Codominant top with included bark	1	2	Improvem
	0902	14	12	Pine (<i>Pinus sp.</i>)	Codominant top with included bark; Suppressed	2	2	Improvem
10	0903	14	17	Pine (<i>Pinus sp.</i>)	Codominant top; Dead and broken branches; Crooked	2	2	Improvem
10	0904	18	17	Pine (<i>Pinus sp.</i>)	Very crooked trunk; Codominant ~6' from ground with included bark; Large codominant trunk leans east; Decay	2	3	Improvem
10	0905	16	18	Pine (<i>Pinus sp.</i>)	Codominant ~10' from ground; Pruned	1	2	Improvem
10	0906	12	14	Pine (<i>Pinus sp.</i>)	Crooked; Pruned; Suppressed	2	2	Improvem
10	0907	17	18	Pine (<i>Pinus sp.</i>)	Crooked; Pruned	1	2	Improvem
10	0908	20	16	Pine (<i>Pinus sp.</i>)	Codominant top; Crooked	1	2	Improvem
10	0909	10	10	Pine (<i>Pinus sp.</i>)	Lean (NE); Crooked; Sweep	2	2	Improvem
10	0910	17	13	Pine (<i>Pinus sp.</i>)	Pruned; Crooked	1	2	Improvem
	0911	17	16	Pine (<i>Pinus sp.</i>)	Codominant top; Crooked; Pruned	1	2	Improvem
	0912	18	13	Pine (Pinus sp.)	Lean (NE); Pruned; Exposed roots	1	2	Improvem
	0913	13	16	Black Oak (Quercus kelloggii)	Codominant top with included bark; Pruned; Large exposed roots	1	2	Improvem
	0915	24	25	Black Oak (Quercus kelloggii)	Bulges; Exposed roots; Pruned; Codominant top	2	2	Improvem
	0917	8	10	Black Oak (Quercus kelloggii)	Canopy (W); Sweep; Pruned	2	2	
		13	18				3	Improvem
	0918		-	Black Oak (Quercus kelloggii)	Bulges; Large exposed roots; Pruned; Topped; Decay	2		Improvem
	0919	13	16	Black Oak (Quercus kelloggii)	Pruned; Large exposed roots; Codominant top	2	2	Improvem -
	1340	15	18	Black Oak (Quercus kelloggii)	Codominant top; Pruned	1	2	Preser
	1341	7	7	Pine (Pinus sp.)	OFFSITE	1	1	Preser
11	1342	17	15	Black Oak (Quercus kelloggii)	Exposed roots	1	2	Preser
11	1343	29	26	Black Oak (Quercus kelloggii)	Codominant ~10' from ground with many branches attached at one point; Exposed roots; Some decay	2	2	Preser
11	1344	16	15	Black Oak (Quercus kelloggii)	Bulges; Pruned	1	2	Preser
11	1345	22	21	Black Oak (Quercus kelloggii)	Some dead branches; Codominant ~6' from ground; Many branches attached at one point	1	2	Preser
11	1346	20	18	Black Oak (Quercus kelloggii)	Some decay; Codominant top with included bark	1	2	Preser
11	1354	6	5	Black Oak (Quercus kelloggii)		1	1	Remov
11	1393	9	4	Maple (<i>Acer sp.</i>)	OFFSITE	1	1	Preser
11	1397	9	12	Maple (Acer sp.)	OFFSITE; Pruned	1	1	Preser
11	1402	8	12	Maple (Acer sp.)	OFFSITE; Pruned	1	1	Preser
	1433	7	7	Black Oak (Quercus kelloggii)	Significant sweep; Lean (N)	1	2	Improven
	1485	7	7	Black Oak (<i>Quercus kelloggii</i>)		1	1	Improvem
	1486	8	7	Black Oak (Quercus kelloggii)		1	1	Improven
	1487	11	10	Black Oak (Quercus kelloggii)		1	1	Improven
	1488	23	27	Black Oak (Quercus kelloggii)	Pruned	1	1	Improven
	1490	21	21	Pine (Pinus sp.)	Lean (E); Exposed roots; Pruned	1	2	Improven
	1490	29	30	Black Oak (Quercus kelloggii)	Some dead and broken branches	1	2	Improven
								'
	1492	22	27	Black Oak (Quercus kelloggii)	Some decay; Some dead and broken branches	2	2	Improven
	1493	20	15	black cottonwood	Broken top; Broken branches	2	2	Improven
	1494	25	27	Black Oak (Quercus kelloggii)	Some dead and broken branches; Codominant top	2	2	Improvem
	1495	6	8	Maple (Acer sp.)		1	1	Improven
	1496	8	12	Maple (Acer sp.)	Many exposed roots	1	1	Improven
11	1497	9	13	Maple (Acer sp.)	OFFSITE; Many exposed roots	1	2	Improven
11	1603	25	28	Black Oak (Quercus kelloggii)	Codominant top; Exposed roots with mechanical damage and decay; Broken branches	2	2	Preser
11	1746	9	13	Maple (Acer sp.)	OFFSITE; Many exposed roots	1	2	Preser
11	1747	6	7	Maple (<i>Acer sp.</i>)	OFFSITE; Many exposed roots	1	2	Preser
11	1758	6	7	Maple (Acer sp.)	OFFSITE; Many exposed roots	1	2	Preser
11	1765	8	9	Maple (Acer sp.)	OFFSITE; Many exposed roots	1	2	Preser
	1766	7	9	Maple (Acer sp.)	OFFSITE; Many exposed roots	1	2	Preser
			 				t	
	1779	7	8	Maple (<i>Acer sp.</i>)	OFFSITE; Many exposed roots	1	2	Improven

THESE TREES ARE UNDER 8" IN DBH AND THEREFORE ARE NOT REGULATED PER TDC 31.060

Total # of Existing Trees Inventoried = 70

Total # of Existing Onsite Trees = 49

Total # of Existing Onsite Trees to be Preserved = 8

Total # of Existing Onsite Trees to be Removed = 41 Total # of Existing Onsite Trees to be Removed that are Exempt= 5

Total # of Existing Onsite Trees to be Removed that are Non-Exempt= 36

Total # of Existing Offsite Trees = 21 Total # of Existing Offsite Trees to be Preserved = 14 Total # of Existing Offsite Trees to be Removed = 7 Total # of Existing Offsite Trees to be Removed that are Exempt= 3

Total # of Existing Offsite Trees to be Removed that are Non-Exempt= 4

*Health Rating:

1 = Good Health - A tree that exhibits typical foliage, bark, and root characteristics, for its respective species, shows no signs of infection or infestation, and has a high level of vigor and vitality.

2 = Fair Health - A tree that exhibits some abnormal health characteristics and/or shows some signs of infection or infestation, but may be reversed or abated with supplemental treatment.

3 = Poor Health - A tree that is in significant decline, to the extent that supplemental treatment would not likely result in reversing or abating its decline.

**Structure Rating:

1 = Good Structure - A tree that exhibits typical physical form characteristics, for its respective species, shows no signs of structural defects of the canopy, trunk, and/or root system.

2 = Fair Structure - A tree that exhibits some abnormal physical form characteristics and/or some signs of structural defects, which reduce the structural integrity of the tree, but are not indicative of imminent physical failure, and may be corrected using arboricultural abatement methods.

3 = Poor Structure - A tree that exhibits extensively abnormal physical form characteristics and/or significant structural defects that substantially reduces the structural viability of the tree, cannot feasibly be abated, and are indicative of imminent physical failure.

***Reason for Removal:

Improvements - Trees that are within the impact limits of proposed improvements.

Poor Condition - Trees that are diseased or defective in a manner that threatens their long term viability. These trees will be replaced per the Landscape Plan in compliance with TDC 74.485.

Arborist Disclosure Statement:

Arborists are tree specialists who use their education, knowledge, training, and experience to examine trees, recommend measures to enhance the health of trees, and attempt to reduce the risk of living near trees. The Client and Jurisdiction may choose to accept or disregard the recommendations of the arborist, or seek additional advice. Arborists cannot detect every condition that could possibly lead to the structural failure of a tree. Trees are living organisms that fail in ways we do not fully understand. Conditions are often hidden within trees and below ground. Arborists cannot guarantee that a tree will be healthy or safe under all circumstances, or for a specified period of time. Likewise, remedial treatments, like medicine, cannot be guaranteed. Trees can be managed, but they cannot be controlled. To live near trees is to accept some degree of risk. The only way to eliminate all risk associated with trees is to eliminate all trees. Neither this author nor AKS Engineering & Forestry, LLC have assumed any responsibility for liability associated with the trees on or adjacent to this site.

At the completion of construction, all trees should once again be reviewed. Land clearing and removal of adjacent trees can expose previously unseen defects and otherwise healthy trees can be damaged during construction.




DATE: 5/3/2019

DAVID J. STEINKE
CERTIFICATE NUMBER: PN-8112A
EXPIRATION DATE: 12/31/21

JOB NUMBER 5736

SHEET




AKS ENGINEERING & FORESTRY, L 12965 SW HERMAN RD STE 100 TUALATIN, OR 97062 P: 503.563.6151 F: 503.563.6152 aks-eng.com

UBL PRELIMINARY FACILITIES I

AS NOTED

JOB NUMBER 5736

SHEET



PH 4 'NDSC

AS NOTED

CHASTER TO THE PROPERTY OF THE COPE ARCHI

JOB NUMBER

5736

SHEET