

Peter van Oss 8160 NE Mauzey CT Hillsboro, OR 97124 (503) 645-2242 13th of April, 2020

RE: Tree inventory and removal plan for Lu Pacific Development.

Lu Pacific Development ATTN: Teresa Long Proposed building construction at: 10005 SW Herman Rd Tualatin, OR 97062

Report Summary:

This report includes the location and status of the trees to be removed for the construction of the proposed buildings. Multi stem trees are marked as one tree with the individual trunk diameters recorded.

General Information:

Lu Pacific Development is proposing to construct two new buildings on the lot located at 10005 SW Herman Rd, Tualatin, OR 97062. The proposed site plan is attached as attachment 1. Purpose of the report:

 Locate and identify the trees that will have to be removed based on the proposed site plan (attachment 1)

Tree Inventory

On 4/13/2020 a pre- construction tree inventory was conducted by myself. The trees were inventoried according to the site plan provided by the customer. All trees over 8" in diameter were recorded. The inventory includes data pertaining to the: tree number, location, DBH at 54", structural condition, comments, treatment recommendation, suggested removals. The trees were tagged and numbered in the field to correspond with the inventory map (attachment 2)

Tree Removals

Typically a tree protection zone is based on the diameter of the tree x 0.5 ft to establish the minimum tree protection zone. For example: a 12" Dbh tree would have a minimum protection

zone of 6' from the trunk extending toward the dripline. Environmental variations and impacts may be cause for adjustment however (root distribution, health, a-typical impacts)

After careful examination of the proposed construction, all trees will have to be removed. All the trees on this site are in development areas per the proposed plan.

Tree Protection

No tree protection fencing will be necessary. All the trees and underbrush will have to be removed under this proposed plan.

Conclusion

48 trees are recommended for removal for the proposed construction of the two buildings by Lu Pacific Development. The trees that are not directly impacted by this plan are number 7 and number 8. The Pines are in poor condition however and do not have a long life expectancy due to the Blue stain fungi caused by the Pine Borer Beetle. The recommendation for all trees is removal.

For detailed summary reports and access to our data, please use the following link:

https://pg-cloud.com/NWTreeSpecialists/?scenario=10005-SW-Herman-Rd-Tualitin

If you have any questions or concerns, please contact me for additional information

Sincerely,

Peter van Oss

NW Tree Specialists

Certified Arborist PN-8145A

ISA Qualified Tree Risk Assessor

1013

503-512-3826 (cell)

peter@nwtreespecialists.com

Addendum:

Attachment 1: Site Plan with Tree removal and Protection

Attachment 2: Inventory Spreadsheet N/A: Tree Protection recommendations

Attachment 4: Assumptions and limiting conditions


Assumptions and Limiting conditions


- 1. A field examination of the site was made on April 13, 2020. My observations and conclusions are as of that date.
- 2. Care has been taken to obtain all information from a reliable source, however the Arborist can neither guarantee nor be responsible for accuracy of information provided by others.
- 3. Unless stated otherwise, information contained in this report covers only those trees that were examined and reflects the condition of those trees at the time of inspection. The inspection is limited to visual examination of the subject trees without dissection, excavation, probing, or coring. There is no warranty or guarantee that problems or deficiencies of the subject tree may not arise in the future.
- 4. All trees possess the risk of failure. Trees can fail at any time, with or without obvious defects or applied stress. Trees are living biological organisms, and I cannot predict nor guarantee their stability or failure.
- 5. Sketches or drawings in this report are intended as visual aids and are not necessarily to scale.
- This report and any values/opinions expressed herein represents my opinion as an arborist. Inaction on the part of those receiving the report is not the responsibility of the Arborist
- 7. Loss or alteration of this report invalidates the entire report.
- 8. The intent of this report is to:
 - a. Provide tree removal findings and recommendations based on the provided site plans and;
 - b. Provide recommendations for correctly protecting trees during construction.

Addendum1

Trees 1,2,4 & 47 are not on the site map and report. They were entered incorrectly in our program in the field. Once a location is marked a number is attached, when you have to delete the incorrectly entered location the program continues the count. For example:

Location 47 marked a blackberry patch, I deleted the entry and that made the Curly Willow location 48.





.0.	2	5									•			1/1
N LOUILOS	LONDINGS	Judipuos	Hed Inds	Table Table	USIS HER	Tues Had	CUBIS HAD	LUBIS HAD	S HORS HERD	S (40)	Suten Cher	Online.	*DNIGUO;	Logensed
3 Common pear	Good	Good	П	17	1 1					15ft-30ft	Pyrus communis	45.3864142	45.3864142 -122.7791672	4
5 Silver maple	Very Poor	Very Poor	20-75%	34.71	16	25	18			50ft-75ft	c	45.38647543	45.38647543 -122.7792704 Remove	Remove
	Dead/Dying	Failed/Failing	20-75%	24						15ft-30ft		45.38654324	45.38654324 -122.7791699	
	Fair	Fair	<25%	18						N/A		45.38638574	45.38638574 -122.7799754 Pine beetle	Pine beetle
	Fair	Fair	25-50%	24						50ft-75ft	Pinus spp.	45.38650442	45.38650442 -122.7800197 Pine beetle	Pine beetle
9 Douglas fir	Poor	Fair	<25%	20						N/A	=	45.38658448	-122.7795999	45.38658448 -122.7795999 May have fir borer
10 Tulip tree	Good	Fair	<52%	18						N/A	Liriodendron tulipifera	45.38672966	-122.779613 Hangers	Hangers
	Poor	Poor	20-75%	16.25	10	80	10			N/A	Acer spp.	45.38670046	45.38670046 -122.7797042 Removal	Removal
	Dead/Dying	Failed/Failing	>15%	26.98	18	8	12	14		15ft-30ft	Prunus persica	45.38667126	45.38667126 -122.7797592	
13 Douglas fir	Excellent	Excellent	<25%	28						30ft-50ft	nenziesii		45.38672139 -122.7798925	
14 Siberian elm	Fair	Poor	25-50%	34.23	20	14	24			30ft-50ft	Ulmus pumila		45.3869352 -122.7799703	
15 Siberian elm	Dead/Dying	Failed/Failing	>75%	24	20	14	24			50ft-75ft	Ulmus pumila	45.38698527	45.38698527 -122.7799153	
16 Siberian elm	Dead/Dying	Failed/Failing	>75%	24	20	14	24			50ft-75ft	Ulmus pumila	45.38701635	45.38701635 -122 7798804	
17 Siberian elm	Poor	Poor	25-50%	10						15ft-30ft	Ulmus pumila	45.38706062	45.38706062 -122.7798616	
18 Douglas fir	Good	Good	<25%	20						50ft-75ft	Pseudotsuga menziesii 45 38708416 -122 7799139	45 38708416	122.7799139	Poison del
19 Douglas fir	Good	Good	<25%	12						30ft-50ft	Pseudotsuga menziesii 45 38711807	45 38711807	-122 7799059	- CISCO - CISC
20 Douglas fir	Good	Good	<25%	14						30ft-50ft	Pseudotsuga menziesii 45 38712372	45 38712372		
21 Douglas fir	Good	Good	<25%	18						30ft-50ft	Pseudotsina menziasii 45 38716422	45 38716422	-122 7799072	
22 Douglas fir	Good	Good	<25%	10						30ft-50ft	Pseudotsuga menziesii 45 38718588	45 38718588	4-122 7799206	
23 Douglas fir	Good	Good	<25%	80						30ft-50ft	Pseudotsuga menziesii 45.38719625	45.38719625	5 -122 7798804	
24 Lombardi poplar	Dead/Dying	Failed/Failing	>75%	48						30ft-50ft	Populus nigra	45.38717647	7 -122 7800132	Hazard
25 Douglas fir	Good	Poor	25-50%	28	8	12	24			30ft-50ft	Pseudotsuga menziesii		3 -122.7800469	
26 Deodar cedar	Good	Good	<25%	47.71	24	38	16			75ft-100ft	Cedrus deodara		45.38697549 -122.7801615	
27 Incense cedar	Good	Good		25.53	10	10	14	16		30ft-50ft	Calocedrus decurrens	45.38702353	3 -122,7802192	
28 Cypress	Good	Good	<25%	49.04	24	20	24	23	18	N/A	Cupressuss spp	45.38696036	45.38696036 -122.7804389	
29 Deodar cedar	Good	Good	<25%	30						50ft-75ft	Cedrus deodara	45.38698956	5 -122.7806522	
30 Siberian elm	Poor	Poor	20-75%	28.84	16	24				50ft-75ft	Ulmus pumila	45.38711727		
31 Siberian elm	Poor	Poor	25-50%	36						30ft-50ft	Ulmus pumila	45.38715452		
Siberian elm	Poor	Poor	25-50%	36						30ft-50ft	Ulmus pumila	45.3871112	45.3871112 -122.7800751	
33 Siberian elm	Poor	Poor	25-50%	16						30ft-50ft	Ulmus pumila	45.3871135	45.3871135 -122.7801699	
34 Douglas fir	Good	Good	<25%	14						50ft-75ft	Pseudotsuga menziesii	45.3871719	45.3871719 -122.7801511	
35 Cherry plum	Fair	Fair	<25%	80						15ft-30ft	Prunus cerasifera	45.3871517	45.3871517 -122.7801891	
36 Douglas fir	Fair	Fair	<25%	12						50ft-75ft	Pseudotsuga menziesii		45.38713945 -122.7802293	
37 Siberian elm	Good	Poor	<25%	28.28	20	20				30ft-50ft	Ulmus pumila	-	45.38727698 -122.7807619	
38 Siberian elm	Good	Fair	<25%	38.57	16	20	24	16		75ft-100ft	Ulmus pumila	45,3874544	45.38745441 -122.7805394	
39 Siberian elm	Good	Fair	<25%	39.45	18	20	16	24		75ft-100ft	Ulmus pumila	45.3875768	45.38757685 -122 7807379	
40 Cherry plum	Very Poor	Very Poor	20-75%	12						15ft-30ft	Prunus cerasifera	45.38776956	45.38776956 -122.7806156	
41 Norway maple	Fair	Fair		10						15ft-30ft	Acer platanoides	45.38779782	2 -122 7805941	
42 Cherry plum	Dead/Dying	Failed/Failing		10						15ft-30ft	Prunus cerasifera	45.38779422		
43 Douglas fir	Good	Good	<25%	28						50ft-75ft	Pseudotsuga menziesii			
44 Siberian elm	Good	Good	<25%	22						50ft-75ft	Ulmus pumila	45,38788353		
45 Siberian elm	Very Poor	Very Poor	20-75%	27.78	16	10	4	12	16	75ft-100ft	Ulmus pumila	45.38781571		
European white birch Dead/Dying	Dond/Duing	The Man Africa Miles of	. 750											
	Deaning	raileo/railing	>12%	14.14	10	10				<15ft	Betula pendula	45.3877734		